



RUBBER INTERTRADE CO.,LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded Parts

NEW PRODUCTS	DATE FEBRUARY-07-2023
---------------------	------------------------------

RBI CODE	OEM NO.	DESCRIPTION	PCS/BOX	PCS/CARTON
324S40WB	48068-BZ080-1	Low. arm bushing DAIHATSU GRAN MAX BIG	4	72
324S40WS	48068-BZ080-2	Low. arm bushing DAIHATSU GRAN MAX SMALL	6	108
413SW18E	41810-52R00-2	Shock absorber rubber SWIFT (2018) (RE,UP,LOW)	12	240
417SW18IZ	44119-57R00	Drive shaft boot SWIFT (2018) INNER	2	100
417SW18UZ	44118-57R00	Drive shaft boot SWIFT (2018) OUTER	2	100
419SW18F	41724-65P00	Shock ABS Mounting Cap SWIFT (2018) UP	20	400
421SW18F	42431-52R00	Stabilizer shaft rubber SUZUKI SWIFT ZC63 (2018) FR	12	288
424SW18WS	45202-53R02-2	Low. arm bushing SWIFT (2018) SMALL	6	108
A13BHS19F	10401259	Shock absorber bearing MG HS (2019) FR	2	32
A13BZS17F	10244443	Shock absorber bearing MG ZS (2017) FR	4	72
A14HS19F	10486951	Shock absorber bumper MG HS (2019) FR	6	72
A14ZS17E1	10297341	Shock absorber bumper MG ZS (2017) RE	6	72
A18PM5LR	10045281-P	Steering gear boot MG5 LH,RH (PP+EPDM)	2	50
A18PM617LR	QFWS0011A-P	Steering gear boot MG6 (2017) LH,RH (PP+EPDM)	2	50
D17PMZ2UA	FA81 22 530A-P	Drive shaft boot MAZDA2,FIESTA OUTER A/T (TPEE)	1	44
D21MZ02F1	CN155484AA	Stabilizer shaft rubber MAZDA2 (2012) DE,(4D,5D SPORT)	8	192
	CN1Z5484B			
	DN21 34 156A			
H38H10L	57789-4H000	Grommet steering rack HYUNDAI H1 LH	6	96
M26XP18EW	4162A409-0	Shock absorber bush XPANDER (2018) NC1W RE	6	108
N17PNR40UZ	39241-EA027-P	Drive shaft boot NAVARA D40T (4WD) OUTER (TPEE)	1	44
N19T32EP	55034-EN101	Coil spring rubber X-TRAIL T31,T32 (2013) RE UP	4	64
N25Y62EP	55045-1LB0A	Suspension bush PATROL Y62 UP RE LH,RH	4	72
	55501-1LB0A-0			
N25Y62EW	551A0-1LB0B-0	Suspension bush PATROL Y62 LOW RE LH,RH	4	72
O14515EI	52722-T8N-T01	Shock dust cover HR-V (2015) RE INNER	2	12
S27XV17EL	20470FL010	Link assy SUBARU XV (2017) RE,LH	2	54
S27XV17ER	20470FL000	Link assy SUBARU XV (2017) RE,RH	2	54
T09AH20LZ	12372-28390-IN	Insulator engine ALPHARD ANH20,ESTIMA ACR50 LH	1	8
T13CR19F	48609-06410	Shock absorber mounting CAMRY ASV71 (2019) FR	1	20
T14AG30F1	48331-58010	Shock absorber bumper ALPHARD AGH30 (2015) FR	6	72



RUBBER INTERTRADE CO.,LTD.

Automotive Rubber Spare Parts and Rubber-to-Metal Bonded Parts

NEW PRODUCTS

DATE FEBRUARY-07-2023

RBI CODE	OEM NO.	DESCRIPTION	PCS/BOX	PCS/CARTON
T14AN10F1	48331-28040	Shock absorber bumper ALPHARD ANH10 (2002-2007),ES	6	72
T25AH30200	48720-58010-0	Suspension bush ALPHARD,VELLFIRE AGH30,AYH30 (20	6	108
T25AH30400	48740-58010-0	Suspension bush ALPHARD,VELLFIRE AGH30,AYH30 (20	6	108
T26F60R	45516-BZ140	Grommet steering bush AVANZA F601 RH	10	180
T27FT15E	48830-0K010	Link assy FORTUNER (2015) RE	2	54
T27KD12FL	48810-60040	Link assy PRADO (2009) GRJ121,KDJ121,TRJ150 FR LH	2	54
T27KD12FR	48820-60050	Link assy PRADO (2009) GRJ121,KDJ121,TRJ150 FR RH	2	54